

## NOTICE TO MARINERS

## NO. 19/2018

## **BUOYS**

General	:	Myanmar-Yangon River Entrance.
Otheran	•	my annual langum my cr Linu ance.

General	•	Tray training Temporal Training Co.						
Delete	:	G Fl.W.2s	New Upper Spit		16°25'.94 N	096°20′.85 E		
Move	:	Fl.R.2s	New Upper Western	from, to ,	16°26'.40 N 16°26'.40 N	096°20'.60 E 096°20'.40 E		
		G F1.W.2s	New Center Spit	from, to ,	16°25'.60 N 16°25'.55 N	096°20'.60 E 096°20'.72 E		
Insert	:	FI.W.4s	New Lower Spit		16°25'.00 N	096°20'.65 E		

**Details** 

- (I) Mariners are recommended to keep New Center Spit and New Lower Spit buoys on the starboard side while entering the channel and on the port side while leaving.
- (II) No entering and leaving without pilot in New Western Channel.

Charts Affected: Admiralty Chart No. 833, MNHC Chart No.09<sup>a</sup>.

**Source** : Myanmar Port Authority, dated 21<sup>st</sup> May, 2018.

Date,30<sup>th</sup> May, 2018

Commanding Officer

Naval Hydrographic Centre

Myanmar Navy.

Mir Their Tint.