

NOTICE TO MARINERS

NO. 19/2019

BUOY

General : Myanmar, Yangon River Approach.

Date, 22nd May, 2019

Delete : Fl.G.Quick Upper Spit 16°26'.60 N , 096° 21'.65 E

Detail : (I) Upper Spit buoy had been drifted by environmental effect and will not be

reinstalled for a period.

(II) The further notice will be promulgated after reinstallation of the buoy.

Charts Affected: Admiralty Chart No. 833, NHC Chart No. 09^a.

Source : Myanmar Port Authority, dated on 7th May, 2019.

Commanding Officer

Ni Their Jint.

Naval Hydrographic Centre

Myanmar Navy.