

FROM:

NHC

TO

DTG: 051210

Date: 5th March, 2020

Notice To Mariners No. 7/2020

MISSING BUOY

General

Myanmar, Tanintharyi Coast.

Delete

.

Conical Buoy

12°29'.550 N, 098° 35'.063 E

Detail

 $(I) \quad \text{The buoy marked for shoal at above position has been missing by environmental} \\$

effect on 17th February 2020.

(II) The further notice will be promulgated after reinstallation of the buoy.

Charts Affected:

Admiralty Charts No. 1075, 824, 216, 830 & 4706.

Source

Myanmar Port Authority, dated on 20th February, 2020.

Hedr

For Commanding Officer

Naval Hydrographic Centre

Myanmar Navy.

Immediate